



BH-0.66 I

Current Transformers


1. General

To be used in combination with measurement instruments: ammeters, watt-hour meters, measurement units, control relays, etc.




2. Operating conditions



- 2.1 Secondary current Isn: 5A
- 2.2 Rated voltage Ue:660 V
- 2.3 Frequency: 50Hz/60Hz
- 2.4 Operating temperature: -5°C to +40°C, humidity <80%
- 2.5 Altitude: ≤1000m
- 2.6 Standards: IEC 61869-2
- 2.7 Installation type: busbar or plate fixing





3. Type designation







4. Technical data

Model	Transformation ratio(I _p /I _{sn}) (A)	Power(VA)		Accuracy class			Number of turns through iron core	Overall and installing dimensions (mm)
		1	0.5	0.5S	0.2	0.2S		
 BH-0.66 Solid type	5/5	2.5	2.5					
10/5	2.5	2.5						
15/5	2.5	2.5						
20/5	2.5	2.5						
25/5	2.5	2.5						
30/5	2.5	2.5						
40/5	2.5	2.5						
50/5	2.5	2.5						
75/5	2.5	2.5						
5/1	2.5	2.5						
10/1	2.5	2.5						
15/1	2.5	2.5						
20/1	2.5	2.5						
25/1	2.5	2.5						
30/1	2.5	2.5						
40/1	2.5	2.5						
50/1	2.5	2.5						
75/1	2.5	2.5						
 BH-0.66 20I	75/5	2.5					1	
100/5	2.5						1	
75/1	2.5	1					1	
100/1	2.5	1					1	
 BH-0.66 30I	30/5	2.5	2.5				5	
50/5	2.5	2.5					3	
75/5	2.5	2.5					2	
100/5	2.5						1	
100/5	5	5					2	
150/5	2.5	2.5					1	
200/5	5	5					1	
250/5	5	5					1	
300/5	5	5					1	
400/5	5	5					1	
30/1	2.5	2.5					5	
50/1	2.5	2.5					3	
75/1	2.5	2.5					2	
100/1	2.5	1					1	
100/1	5	5					2	
150/1	2.5	2.5					1	
200/1	5	5					1	
250/1	5	5					1	
300/1	5	5					1	

Model	Transformation ratio (I _{pn} /I _{sn}) (A)	Power (VA)		Accuracy class			Number of turns through iron core	Overall and installing dimensions (mm)
		1	0.5	0.5S	0.2	0.2S		
 BH-0.66 30IB	30/5	5	2.5	2.5	2.5	2.5	5	
	50/5	5	2.5	2.5	2.5	2.5	3	
	75/5	5	2.5	2.5	2.5	2.5	2	
	75/5	5	2.5	2.5	2.5	2.5	1	
	100/5	5	2.5	2.5	2.5	2.5	1	
	100/5	5	5	5	5	5	2	
	150/5	5	2.5	2.5	2.5	2.5	1	
	200/5	5	5	5	5	5	1	
	250/5	5	5	5	5	5	1	
	300/5	5	5	5	5	5	1	
	30/1	2.5	1				5	
	50/1	2.5	1				3	
	75/1	5	2.5				2	
	100/1	5	2.5				2	
	150/1	5	2.5				1	
	200/1	5	5				1	
	250/1	5	5				1	
 BH-0.66 40I	30/5	2.5	2.5	2.5	2.5	2.5	5	
	50/5	2.5	2.5	2.5	2.5	2.5	3	
	75/5	2.5	2.5	2.5	2.5	2.5	2	
	100/5	2.5					1	
	100/5	5	5	5	5	2.5	2	
	150/5	2.5	2.5	2.5	2.5	2.5	1	
	200/5	5	5	5	5	2.5	1	
	250/5	5	5	5	5	2.5	1	
	300/5	5	5	5	5	5	1	
	400/5	5	5	5	5	5	1	
	500/5	10	10	5	5	5	1	
	600/5	10	10	5	5	5	1	
	30/1	5	2.5	5	5	5	5	
	50/1	5	2.5				3	
	75/1	5	2.5				2	
	100/1	5	5				2	
	150/1	5	2.5				1	
	200/1	5	5				1	
	250/1	5	5				1	
	300/1	5	5				1	
	400/1	5	5				1	
	500/1	10	10				1	

Model	Transformation ratio(I _p n/I _s n) (A)	Power(VA) Accuracy class					Number of turns through iron core	Overall and installing dimensions (mm)
		1	0.5	0.5S	0.2	0.2S		
	150/5	2.5					1	
	200/5	5	2.5	2.5	2.5	2.5	1	
	250/5	5	5	2.5	2.5	2.5	1	
	300/5	5	5	5	5	5	1	
	400/5	5	5	5	5	5	1	
	500/5	10	10	5	5	5	1	
	600/5	10	10	5	5	5	1	
	750/5	10	10	10	10	5	1	
	800/5	10	10	10	10	5	1	
	1000/5	10	10	10	10	5	1	
	1200/5	20	20	20	20	5	1	 (750/5A~1500/5A class 1 class 0.5)
	150/1	2.5					1	
	200/1	5	2.5				1	
	250/1	5	5				1	
	300/1	5	5				1	
	400/1	5	5				1	
	500/1	10	10				1	
	600/1	10	10				1	
	750/1	10	10				1	
	800/1	10	10				1	
	1000/1	10	10				1	
	200/5	5	2.5	2.5	2.5	2.5	1	
	250/5	5	5	2.5	2.5	2.5	1	
	300/5	5	5	5	5	2.5	1	
	400/5	5	5	5	5	5	1	
	500/5	10	10	5	5	5	1	
	600/5	10	10	5	5	5	1	
	750/5	10	10	10	10	5	1	
	800/5	10	10	10	10	5	1	
	1000/5	10	10	10	10	5	1	
	1200/5	20	20	20	20	5	1	
	1500/5	20	20	20	20	10	1	 (1500/5A~2000/5A class 1 class 0.5)
	2000/5	20	20	20	20	10	1	
	200/1	5					1	
	250/1	5	5				1	
	300/1	5	5				1	
	400/1	5	5				1	
	500/1	10	10				1	
	600/1	10	10				1	
	750/1	10	10				1	
	800/1	10	10				1	
	1000/1	10	10				1	
	1200/1	20	20				1	

Model	Transformation ratio(I _{pn} /I _{sn}) (A)	Power(VA) Accuracy class					Number of turns through iron core	Overall and installing dimensions (mm)
		1	0.5	0.5S	0.2	0.2S		
 BH-0.66 80I	300/5	5	5	2.5	2.5	2.5	1	 (2000/5A~2500/5A class 1 class 0.5)
400/5	5	5	2.5	2.5	2.5	2.5	1	
500/5	10	10	5	5	5	5	1	
600/5	10	10	5	5	5	5	1	
750/5	10	10	10	10	5	5	1	
800/5	10	10	10	10	5	5	1	
1000/5	10	10	10	10	5	5	1	
1200/5	20	20	20	20	5	5	1	
1500/5	20	20	20	20	10	10	1	
2000/5	20	20	20	20	10	10	1	
2500/5	40	40	40	40	10	10	1	
300/1	5	5					1	
400/1	5	5					1	
500/1	10	10					1	
600/1	10	10					1	
 BH-0.66 100I	600/5	10	10	10	10	5	1	 (2500/5A~3000/5A class 1 class 0.5)
750/5	10	10	10	10	5	5	1	
800/5	10	10	10	10	5	5	1	
1000/5	10	10	10	10	5	5	1	
1200/5	20	20	20	20	5	5	1	
1500/5	20	20	20	20	10	10	1	
2000/5	20	20	20	20	10	10	1	
2500/5	40	40	40	40	10	10	1	
3000/5	40	40	40	40	10	10	1	
600/1	10	10					1	
750/1	10	10					1	
800/1	10	10					1	
 BH-0.66 120I	1000/5	10	10	10	10	5	1	 (2500/5A~4000/5A class 1 class 0.5)
1200/5	20	20	20	20	5	5	1	
1500/5	20	20	20	20	10	10	1	
2000/5	20	20	20	20	10	10	1	
2500/5	40	40	40	40	10	10	1	
3000/5	40	40	40	40	10	10	1	
4000/5	40	40	40	40	10	10	1	
1000/1	10	10					1	
1200/1	20	20					1	
1500/1	20	20					1	
2000/1	20	20					1	
2500/1	40	40					1	
3000/1	40	40					1	

